

Oil Field Environmental Incident Summary

Incident: 20140117180419 **Date/Time of Notice:** 01/17/2014 17:29

Responsible Party: Summit Midstream Partners, LLC.

Well Operator:

Well Name: North Compressor Station

Field Name:

Well File #: 0

Date Incident: 1/17/2014 **Time Incident:** 14:00

Facility ID Number:

County: BURKE

Twp: 159

Rng: 91

Sec: 25

Qtr: SE SE

Location Description: The North Compressor Station is located in Burke County. The facility is owned and operated by Summit Midstream Partners, LLC.

Submitted By: Andrew Parisi

Received By:

Contact Person: Andrew Parisi
999 18th Street,
Suite 3400S
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

3 MCF of natural gas

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

The release did not impact any soil or water. The release dispersed immediately in the air and did not cause an explosive atmosphere.

Action Taken or Planned:

The leaking valve was repaired within about 30 minutes after the facility was shut down and isolated. The facility was placed back into operation after the leaking valve was fixed.

Wastes Disposal Location: N/A

Agencies Involved:

Updates

Date: 1/21/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Follow-up is necessary. Natural gas leak reported, but question regarding natural gas liquids involved needs to be asked.

Date: 1/24/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/24/2014 at 12:24, on location. According to onsite personnel, during installation of new equipment valve was accidentally hit and pipe was damaged, causing release. No noticeable impact to snow/ground beneath valve and piping. According to onsite personnel, pipe will be replaced and valve handle removed.